

GDC 155 Professional



en Original instructions

hi मूल ऑपरेटगि मैनुअल

Robert Bosch Power Tools GmbH 70538 Stuttgart GERMANY

ALI (WAIVI


www.bosch-pt.com


1609 92A 54C (2019.07) PS / 14



2|


English Page	5
हिंदी पेज	10








Bosch Power Tools 1 609 92A 54C | (10.07.2019)











1 609 92A 54C | (10.07.2019) Bosch Power Tools

English

Safety instructions

General Power Tool Safety Warnings

▲ WARNING Read all safety warnings and all instructions. Failure to follow the

warnings and instructions may result in electric shock, fire and/or serious injury.

Save all warnings and instructions for future reference.

The term "power tool" in the warnings refers to your mainsoperated (corded) power tool or battery-operated (cordless) power tool.

Work area safety

- Keep work area clean and well lit. Cluttered or dark areas invite accidents.
- ▶ Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases or dust. Power tools create sparks which may ignite the dust or fumes.
- Keep children and bystanders away while operating a power tool. Distractions can cause you to lose control.

Electrical safety

- ► Power tool plugs must match the outlet. Never modify the plug in any way. Do not use any adapter plugs with earthed (grounded) power tools. Unmodified plugs and matching outlets will reduce risk of electric shock.
- Avoid body contact with earthed or grounded surfaces, such as pipes, radiators, ranges and refrigerators. There is an increased risk of electric shock if your body is earthed or grounded.
- Do not expose power tools to rain or wet conditions.
 Water entering a power tool will increase the risk of electric shock.
- ▶ Do not abuse the cord. Never use the cord for carrying, pulling or unplugging the power tool. Keep cord away from heat, oil, sharp edges or moving parts.
 Damaged or entangled cords increase the risk of electric shock.
- ➤ When operating a power tool outdoors, use an extension cord suitable for outdoor use. Use of a cord suitable for outdoor use reduces the risk of electric shock.
- If operating a power tool in a damp location is unavoidable, use a residual current device (RCD) protected supply. Use of an RCD reduces the risk of electric shock.

Personal safety

Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use a power tool while you are tired or under the influence of drugs, alcohol or medication. A moment of inattention while operating power tools may result in serious personal injury.

- Use personal protective equipment. Always wear eye protection. Protective equipment such as dust mask, non-skid safety shoes, hard hat, or hearing protection used for appropriate conditions will reduce personal injuries.
- ▶ Prevent unintentional starting. Ensure the switch is in the off-position before connecting to power source and/or battery pack, picking up or carrying the tool. Carrying power tools with your finger on the switch or energising power tools that have the switch on invites accidents.
- ► Remove any adjusting key or wrench before turning the power tool on. A wrench or a key left attached to a rotating part of the power tool may result in personal injury.
- ➤ Do not overreach. Keep proper footing and balance at all times. This enables better control of the power tool in unexpected situations.
- ▶ Dress properly. Do not wear loose clothing or jewellery. Keep your hair, clothing and gloves away from moving parts. Loose clothes, jewellery or long hair can be caught in moving parts.
- ► If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used. Use of dust collection can reduce dust-related hazards.

Power tool use and care

- ➤ Do not force the power tool. Use the correct power tool for your application. The correct power tool will do the job better and safer at the rate for which it was designed.
- ➤ Do not use the power tool if the switch does not turn it on and off. Any power tool that cannot be controlled with the switch is dangerous and must be repaired.
- Disconnect the plug from the power source and/or the battery pack from the power tool before making any adjustments, changing accessories, or storing power tools. Such preventive safety measures reduce the risk of starting the power tool accidentally.
- ➤ Store idle power tools out of the reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool. Power tools are dangerous in the hands of untrained users.
- Maintain power tools. Check for misalignment or binding of moving parts, breakage of parts and any other condition that may affect the power tool's operation. If damaged, have the power tool repaired before use. Many accidents are caused by poorly maintained power tools.
- ► Keep cutting tools sharp and clean. Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.
- Use the power tool, accessories and tool bits etc. in accordance with these instructions, taking into account the working conditions and the work to be per-

Bosch Power Tools 1 609 92A 54C | (10.07.2019)



6 | English

formed. Use of the power tool for operations different from those intended could result in a hazardous situation.

Service

► Have your power tool serviced by a qualified repair person using only identical replacement parts. This will ensure that the safety of the power tool is maintained.

Cut-off machine safety warnings

- ▶ The guard provided with the tool must be securely attached to the power tool and positioned for maximum safety, so the least amount of wheel is exposed towards the operator. Position yourself and bystanders away from the plane of the rotating wheel. The guard helps to protect operator from broken wheel fragments and accidental contact with wheel.
- ► Use only bonded diamond cut-off wheels for your power tool. Just because an accessory can be attached to your power tool, it does not assure safe operation.
- ➤ The rated speed of the accessory must be at least equal to the maximum speed marked on the power tool. Accessories running faster than their rated speed can break and fly apart.
- ▶ Wheels must be used only for recommended applications. For example: do not grind with the side of cut-off wheel. Abrasive cut-off wheels are intended for peripheral grinding, side forces applied to these wheels may cause them to shatter.
- Always use undamaged wheel flanges that are of correct diameter for your selected wheel. Proper wheel flanges support the wheel thus reducing the possibility of wheel breakage.
- ▶ Do not use worn down reinforced wheels from larger power tools. Wheels intended for a larger power tool are not suitable for the higher speed of a smaller tool and may burst.
- ➤ The outside diameter and the thickness of your accessory must be within the capacity rating of your power tool. Incorrectly sized accessories cannot be adequately guarded or controlled.
- ➤ The arbour size of wheels and flanges must properly fit the spindle of the power tool. Wheels and flanges with arbour holes that do not match the mounting hardware of the power tool will run out of balance, vibrate excessively and may cause loss of control.
- ▶ Do not use damaged wheels. Before each use, inspect the wheels for chips and cracks. If power tool or wheel is dropped, inspect for damage or install an undamaged wheel. After inspecting and installing the wheel, position yourself and bystanders away from the plane of the rotating wheel and run the power tool at maximum no load speed for one minute. Damaged wheels will normally break apart during this test time.
- Wear personal protective equipment. Depending on application, use face shield, safety goggles or safety glasses. As appropriate, wear dust mask, hearing protectors, gloves and shop apron capable of stopping

- small abrasive or workpiece fragments. The eye protection must be capable of stopping flying debris generated by various operations. The dust mask or respirator must be capable of filtrating particles generated by your operation. Prolonged exposure to high intensity noise may cause hearing loss.
- ➤ Keep bystanders a safe distance away from work area. Anyone entering the work area must wear personal protective equipment. Fragments of workpiece or of a broken wheel may fly away and cause injury beyond immediate area of operation.
- ► Hold the power tool by insulated gripping surfaces only, when performing an operation where the cutting accessory may contact hidden wiring or its own cord. Cutting accessory contacting a "live" wire may make exposed metal parts of the power tool "live" and could give the operator an electric shock.
- ▶ Position the cord clear of the spinning accessory. If you lose control, the cord may be cut or snagged and your hand or arm may be pulled into the spinning wheel.
- Never lay the power tool down until the accessory has come to a complete stop. The spinning wheel may grab the surface and pull the power tool out of your control.
- ▶ Do not run the power tool while carrying it at your side. Accidental contact with the spinning accessory could snag your clothing, pulling the accessory into your body.
- Regularly clean the power tool's air vents. The motor's fan will draw the dust inside the housing and excessive accumulation of powdered metal may cause electrical hazards.
- ➤ Do not operate the power tool near flammable materials. Sparks could ignite these materials.
- ▶ Do not use accessories that require liquid coolants. Using water or other liquid coolants may result in electrocution or shock.

Kickback and related warnings

Kickback is a sudden reaction to a pinched or snagged rotating wheel. Pinching or snagging causes rapid stalling of the rotating wheel which in turn causes the uncontrolled power tool to be forced in the direction opposite of the wheel's rotation at the point of the binding.


For example, if an abrasive wheel is snagged or pinched by the workpiece, the edge of the wheel that is entering into the pinch point can dig into the surface of the material causing the wheel to climb out or kick out. The wheel may either jump toward or away from the operator, depending on direction of the wheel's movement at the point of pinching. Abrasive wheels may also break under these conditions.

Kickback is the result of power tool misuse and/or incorrect operating procedures or conditions and can be avoided by taking proper precautions as given below.

Maintain a firm grip on the power tool and position your body and arm to allow you to resist kickback forces. Always use auxiliary handle, if provided, for maximum control over kickback or torque reaction

1 609 92A 54C | (10.07.2019) Bosch Power Tools





- ► Never place your hand near the rotating accessory. Accessory may kickback over your hand.
- ➤ Do not position your body in line with the rotating wheel. Kickback will propel the tool in direction opposite to the wheel's movement at the point of snagging.
- ▶ Use special care when working corners, sharp edges etc. Avoid bouncing and snagging the accessory. Corners, sharp edges or bouncing have a tendency to snag the rotating accessory and cause loss of control or kickback.
- ➤ Do not attach a saw chain, woodcarving blade, segmented diamond wheel with a peripheral gap greater than 10 mm or toothed saw blade. Such blades create frequent kickback and loss of control.
- ▶ Do not "jam" the wheel or apply excessive pressure.
 Do not attempt to make an excessive depth of cut.
 Overstressing the wheel increases the loading and susceptibility to twisting or binding of the wheel in the cut and the possibility of kickback or wheel breakage.
- ▶ When wheel is binding or when interrupting a cut for any reason, switch off the power tool and hold the power tool motionless until the wheel comes to a complete stop. Never attempt to remove the wheel from the cut while the wheel is in motion otherwise kickback may occur. Investigate and take corrective action to eliminate the cause of wheel binding.
- ➤ Do not restart the cutting operation in the workpiece. Let the wheel reach full speed and carefully re-enter the cut. The wheel may bind, walk up or kickback if the power tool is restarted in the workpiece.
- ➤ Support panels or any oversized workpiece to minimize the risk of wheel pinching and kickback. Large workpieces tend to sag under their own weight. Supports must be placed under the workpiece near the line of cut and near the edge of the workpiece on both sides of the wheel.
- Use extra caution when making a "pocket cut" into existing walls or other blind areas. The protruding wheel may cut gas or water pipes, electrical wiring or objects that can cause kickback.

Additional Safety Information





Wear hearing protection, protective goggles, a dust mask and gloves. Use at least an FFP 2 protection class particle-fil-

tering half mask.

- Use clamps or another practical way to secure and support the workpiece to a stable platform. Holding the work by your hand or against the body leaves it unstable and may lead to loss of control.
- ▶ Use suitable detectors to determine if utility lines are hidden in the work area or call the local utility company for assistance. Contact with electric lines can lead to fire and electric shock. Damaging a gas line can lead to

- explosion. Penetrating a water line causes property damage or may cause an electric shock.
- ► Do not touch the cutting disc after use before it has cooled. The cutting disc becomes very hot during use.
- ► Hold the power tool firmly with both hands and make sure you have a stable footing. The power tool can be more securely guided with both hands.

Products sold in GB only:

Your product is fitted with an BS 1363/A approved electric plug with internal fuse (ASTA approved to BS 1362). If the plug is not suitable for your socket outlets, it should be cut off and an appropriate plug fitted in its place by an authorised customer service agent. The replacement plug should have the same fuse rating as the original plug. The severed plug must be disposed of to avoid a possible shock hazard and should never be inserted into a mains socket elsewhere.

Product Description and Specifications



Read all the safety and general instructions. Failure to observe the safety and general instructions may result in electric shock, fire and/or serious injury.

Please observe the illustrations at the beginning of this operating manual.


Intended Use

The power tool is intended to be used on a stable surface, with the base plate and the protective guard fitted, to cut or score horizontally into predominantly mineral materials, e.g. marble, without using water. The power tool is not suitable for cutting wood, plastic or metal.

Product Features

The numbering of the product features refers to the diagram of the power tool on the graphics page.

- (1) On/off switch
- (2) Lock-on button for on/off switch
- (3) Handle (insulated gripping surface)
- (4) Cutting depth scale
- (5) Wing bolt for preselecting the cutting depth
- (6) Diamond cutting disc^{A)}
- (7) Direction-of-rotation arrow for grinding spindle
- (8) Protective guard
- (9) Base plate
- (10) Drive spindle
- (11) O-ring
- (12) Mounting flange
- (13) Clamping flange
- (14) Ring spanner
- (15) Clamping bolt







8 | English

- (16) Hex key
- (17) Covering caps
- (18) Carbon brushes
- A) Accessories shown or described are not included with the product as standard. You can find the complete selection of accessories in our accessories range.

Technical Data

Masonry saw		GDC 155
Article number		3 601 CA0 2F.
Rated power input	W	1550
No-load speed	min ⁻¹	8600
Max. diamond cutting disc diameter	mm	150-155
Min. cutting disc thickness	mm	1.6
Max. cutting disc thickness	mm	2.2
Locating bore	mm	20
Max. cutting depth	mm	47
Weight according to EPTA- Procedure 01:2014	kg	3.4
Protection class		

The specifications apply to a rated voltage [U] of 230 V. These specifications may vary at different voltages and in country-specific models

Assembly

► Pull the plug out of the socket before carrying out any work on the power tool.

Dust/Chip Extraction

Dust from materials such as lead-containing coatings, some wood types, minerals and metal can be harmful to one's health. Touching or breathing-in the dust can cause allergic reactions and/or lead to respiratory infections of the user or bystanders.

Certain dust, such as oak or beech dust, is considered carcinogenic, especially in connection with wood-treatment additives (chromate, wood preservative). Materials containing asbestos may only be worked by specialists.

- Provide for good ventilation of the working place.
- It is recommended to wear a P2 filter-class respirator.

Observe the relevant regulations in your country for the materials to be worked.

Avoid dust accumulation at the workplace. Dust can easily ignite.

Mounting/changing the diamond cutting disc (see figure A)

- Wearing protective gloves while inserting and replacing diamond cutting discs is recommended.
- ▶ Diamond cutting discs become very hot while working; do not touch them until they have cooled.

- Always use a diamond cutting disc of the correct size and with the correct locating bore as specified in the technical data
- Use only diamond-tipped cutting discs. Segmented diamond cutting discs may only exhibit negative cutting angles and max. 10 mm slots between the segments

Mounting the diamond cutting disc

- Clean the diamond cutting disc (6) and all the clamping elements to be fitted.
- Fit the mounting flange (12) with the O-ring (11) to the drive spindle (10).
- Place the diamond cutting disc (6) on the mounting flange (12). The direction of the arrow on the diamond cutting disc (6) must match the direction-of-rotation arrow on the protective guard (8).
- Fit the clamping flange (13) and screw in the clamping bolt (15).
- Use the ring spanner (14) to hold the clamping flange (13) and use the hex key (16) to tighten the clamping bolt (15).

Removing the Diamond Cutting Disc

- Use the ring spanner (14) to hold the clamping flange (13) and use the hex key (16) to loosen the clamping bolt (15).
- Remove the clamping flange (13) and the diamond cutting disc (6) from the drive spindle (10).

Operation

Operating Modes

- Pull the plug out of the socket before carrying out any work on the power tool.
- ▶ Hold the power tool by insulated gripping surfaces only, when performing an operation where the cutting accessory may contact hidden wiring or its own cord. Cutting accessory contacting a "live" wire may make exposed metal parts of the power tool "live" and could give the operator an electric shock.

Preselecting the Cutting Depth (see figure B)

The cutting depth must only be preselected while the power tool is switched off.


Adapt the cutting depth to the thickness of the workpiece. To achieve an optimal result, the diamond cutting disc needs to protrude from the material by approx. 2 mm.

Loosen the wing bolt (5). For a smaller cutting depth, pull
the power tool away from the base plate (9); for a larger
cutting depth, push the power tool towards the base plate
(9). Set the required cutting depth on the scale (4).
Retighten the wing bolt (5).

Starting Operation

Pay attention to the mains voltage. The voltage of the power source must match the voltage specified on the

1 609 92A 54C | (10.07.2019) Bosch Power Tools



▶ Products that are only sold in AUS and NZ: Use a residual current device (RCD) with a nominal residual current of 30 mA or less.

Switching On/Off

- To switch on the power tool, press and hold the on/off switch (1).
- Press the lock-on button (2) to lock the on/off switch (1) in this position.
- To switch off the power tool, release the on/off switch
 (1); or, if the switch is locked with the lock-on button
 (2), briefly press the on/off switch
 (1) and then release it.
- ► Check the diamond cutting disc before using it. The diamond cutting disc must be fitted properly and be able to rotate freely. Carry out a test run for at least one minute with no load. Do not use diamond cutting discs that are damaged, run untrue or vibrate during use. Damaged diamond cutting discs can burst apart and cause injuries.

Practical Advice

- Exercise caution when cutting slots in structural walls; see the "Information on structural design" section.
- Do not load the power tool so heavily that it comes to a stop.
- If the power tool has been subjected to a heavy load, continue to run it at no-load for several minutes to cool down the accessory.
- ▶ Work with cutting depths greater than 20 mm in hard materials, e.g. concrete, over several work operations, so as not to overload the motor.
- Clamp the workpiece if it is not secure under its own weight.
- ► The power tool may only be used for dry cutting.
- ► Diamond cutting discs become very hot while working; do not touch them until they have cooled.

Protect the cutting disc against impact, shock and grease. Do not subject the cutting disc to lateral pressure.

Do not attempt to reduce the speed of a diamond cutting disc coming to a stop by applying pressure from the side. When cutting especially hard materials such as concrete with a high pebble content, the diamond cutting disc can overheat and become damaged as a result. This is clearly indicated by circular sparking, rotating with the diamond cutting disc.

If this happens, stop cutting and allow the diamond cutting disc to cool down by running the power tool for a short time at maximum speed with no load.

If work is noticeably slower and with circular sparking, this indicates that the diamond cutting disc that has become dull. You can resharpen the disc by briefly cutting into abrasive material (e.g. lime-sand brick).

Cutting Direction (see figure C)

The power tool must always work in an up-grinding motion. Otherwise there is a risk that it will be pushed **uncontrolled** out of the cut.

Information on Structural Design

Slots in load-bearing walls are subject to DIN 1053 part 1 or country-specific regulations. These regulations must be observed under all circumstances. Seek advice from the responsible structural engineer, architect or construction supervisor before starting work.

Maintenance and Service

Maintenance and cleaning

- ► Pull the plug out of the socket before carrying out any work on the power tool.
- ➤ To ensure safe and efficient operation, always keep the power tool and the ventilation slots clean.

In order to avoid safety hazards, if the power supply cord needs to be replaced, this must be done by **Bosch** or by an after-sales service centre that is authorised to repair **Bosch** power tools.

Replacing the carbon brushes (see figure D)

Check the length of the carbon brushes around every 2–3 months and replace both carbon brushes if required.

Never replace only a single carbon brush.

Note: Only use carbon brushes supplied by Bosch and intended specifically for your product.

- Unscrew the caps (17) using a suitable screwdriver.
- Replace the spring-loaded carbon brushes **(18)** and screw on the caps again.

After-Sales Service and Application Service

Our after-sales service responds to your questions concerning maintenance and repair of your product as well as spare parts. You can find explosion drawings and information on spare parts at: www.bosch-pt.com

The Bosch product use advice team will be happy to help you with any questions about our products and their accessories.

In all correspondence and spare parts orders, please always include the 10-digit article number given on the nameplate of the product.

India

Bosch Service Center

69, Habibullah Road, (Next to PSBB School), T. Nagar Chennai-600077

Phone: (044) 64561816 Bosch Service Center 18, Community Center Phase 1, Mayapuri New Delhi–110064 Phone: (011) 43166190

1 609 92A 54C | (10.07.2019)





10 | हिंदी

Disposal

The power tool, accessories and packaging should be recycled in an environmentally friendly manner.



Do not dispose of power tools along with household waste.

हर्दिी

सुरक्षा नरि्देश

पॉवर टूल सुरक्षा की सामान्य चेतावनयिां

ा चेतावनियाँ सभी सुरक्षा चेतावनी और सभी निर्देश पहें। चेतावनियाँ और निर्देशों का अनुसरण करने में विफल होने के परिणामस्वरूप इलेक्ट्रिक शॉक, आग लगना और/या कोई गंभीर हानि हो सकती है। भावी संदर्भ के लिए सभी चेतावनी और निर्देश सहेजें। चेतावनी में दी गई टर्म "पॉवर टूल" आपके मुख्य तार द्वारा संचालित (तार सहित) पॉवर टूल या बैटरी संचालित (तार रहित) पॉवर टूल से संबंधित है।

कार्य क्षेत्र सुरक्षा

- ► कार्य क्षेत्र साफ और अच्छी तरह उजला रखें। अव्यवस्थिति या अंधकारपूर्ण क्षेत्र दुर्घटनाओं को आमंत्रित करते हैं।
- पॉवर टूल्स को विस्फोटक वातावरण जैसे कि, ज्वलनशील द्रव्यों, गैसों या राख की उपस्थिति में संचालित न करें। पॉवर टूल्स से चिगारी निकलती है, जो कचरे या धुएं में आग लगा सकती है।
- पॉवर टूल संचालित करते समय बच्चों और आसपास खड़े लोगों को दूर रखें। ध्यान भंग होने के कारण आपका नर्यित्रण खो सकत हैं।

वद्यित सुरक्षा

- पॉवर टूल पुलग आउटलेट से मेल खाना चाहिए।पुलग को किसी भी सुथति में न सुधारें।ऐसे किसी एडॉप्टर का उपयोग न करें, जिस भूसंपर्कति (ज़मीन में) पॉवर टूल्स के साथ पुलग किया गया हो। अपरविर्तति पुलग और मेल खाते हुए आउटलेट बजिली के झटके का जोखिम कम करेंगे।
- अर्थिंग की गई या ज़मीन पर पड़ी चीज़ों, जैसे पाइप, रेडिएटर, रेंज और रेफ़्रिजिरेटर के साथ संपर्क में आने से बचें। यद आपका शरीर ज़मीन के या ज़मीन पर पड़ी किसी वस्तु के संपर्क में आता है, तो बजिली के झटके का खतरा बढ़ जाता है।
- पॉवर टूल्स को बारिश या गीली स्थितियों में खुला न रखें।
 पॉवर टूल में पानी घुस जाने से बिजली का झटका लगने का ख़तरा बढ़ जाएगा।
- कॉर्ड का अधिक दुरुपयोग न करें।कॉर्ड का उपयोग कोई चीज़ ले जाने, खींचने या पॉवर टूल को अनप्लग करने में कभी भी न करें।कॉर्ड को ऊष्मा, तेल, तेज़ धार या गतिमान पुर्ज़ों से दूर रखें। क्षतिग्रस्त या उलझी हुई कॉर्ड से बजिली के झटके का ख़तरा बढ़ जाता है।
- पॉवर टूल को आउटडोर में संचालित करते समय, आउटडोट के उपयोग हेतु उपयुक्त एक्स्टेंशन कॉर्ड का उपयोग करें।

- आउटडोर उपयोग के लिए उपयुक्त कॉर्ड का उपयोग करना बजिली के झटके का जोखिम कम करता है।
- यदि पॉवर टूल को सीलनभरी जगह पर संचालित करना अनिवार्य हो तो, रेसी इ्यूअल करंट डिवाइस (RCD) संरक्षिति सप्लाई का उपयोग करें। RCD का उपयोग बिजली के झटके के जोखिम को कम करता है।

व्यक्तगित सुरक्षा

- पॉवर टूल संचालित करते समय सजग रहें, अपने काम पर ध्यान दें और व्यावहारिक ज्ञान का उपयोग करें। थके होने पर या दवाओं, अल्होकॉल या औषध-िप्रयोग के प्रभाव में होने पर पॉवर टूल का उपयोग न करें। पॉवर टूल संचालित करने के दौरान असावधान रहने पर व्यक्तिगत रूप से गंभीर चोट आ सकती है।
- च्यक्तिगत सुरक्षा उपकरण का उपयोग करें। आँखों की सुरक्षा के लिए हमेशा कुछ पहनें। सुरक्षा उपकरण, जैसे धूल मासक, फिसलन रहित सुरक्षा ज्ते, मजबूत टोपी, या उचित परिस्थितियों के लिए उपयोग की जाने वाली कानों की सुरक्षा जैसे सुरक्षा उपकरण व्यक्तिगत हानि को कम कर देंगे।
- अनजाने में शुरू करने से बचें।पॉवर सोर्स और/या बैटरी पैक को कनेक्ट करने, टूल को उठाने या ले जाने से पहले सुनिश्चिति कर लें कि स्विच बंद स्थिति मैं है। पॉवर टूल ले जाते समय स्विच पर उंगली होना या चालू स्विच में पॉवर टूल को लगाना दुर्घटनाओं को आमंत्रति कर सकता है।
- पॉवर टूल को चालू करने से पहले किसी भी समायोजन कुंजी निकाल दें या खींच लें। पॉवर टूल के घूमने वाले भाग से जुड़ी कोई कुंजी खींचने या निकालने से व्यक्तिगत हान हो सकती है।
- अति-विशिवास से बचें।हर समय पैरों को ठीक से जमाए रखें और संतुलन में रखें। ऐसा करना अनपेक्षित स्थितियों में पॉवर टूल के नियंतरण को और बेहतर बनाता है।
- कपड़े अच्छे-से पहनें।ढीले कपड़े या आभूषण न पहनें।अपने बालों, कपड़ों और दस्तानों को चलित पुर्ज़ों से दूर रखें।ढीले कपड़े, आभूषण या लंबे बाल चलित पुर्ज़ों में फँस सकते हैं।
- यदि उपकरण धूल निष्कर्षण और सुविधा संग्रह के कनेक्शन के लिए प्रदान किए जाते हैं, तो सुनिश्चिति करें कि वो कनेक्ट हों और उचित रूप से उपयोग किए जाते हों। धूल संग्रह का उपयोग करना धूल-संबंधी ख़तरों को कम कर सकता है।

पॉवर टूल उपयोग और देखभाल

- पॉवर टूल पर ज़ोर न लगाएं।अपनी एप्लिकशन के लिए सही
 पॉवर टूल का उपयोग करें। सही पॉवर टूल जिसके लिए बनाया
 गया था. उसके हसि।ब से बेहतर और सरकषित कारय करेगा।
- यदिस्विच चालू और बंद न होता हो, तो पॉवर टूल का उपयोग न करें। ऐसा कोई भी पॉवर टूल जिस स्विच से निर्येत्रित नहीं किया जा सकता है, ख़तरानाक है और उसे सुधारा जाना चाहिए।
- कोई भी समायोजन करने, सामान बदलने या बजिली उपकरण का भंडारण करने से पहले पॉवर उपकरण से बजिली के स्रोत और/या बैटरी उपकरण से प्लग को डिस्किनेक्ट करें। इस तरह के सुरक्षात्मक उपाय पॉवर टूल के अचानक चालू हो जाने के जोखिम को कम करते हैं।
- तिष्क्रिय पॉवर टूल्स को बच्चों की पहुंच से बाहर रखें और पॉवर टूल चलाने के लिए बिजिली के उपकरण या इन निर्देशों से अनमिज्ञ लोगों को अनुमति दें। अप्रशक्षिति उपयोगकर्ताओं के हाथों में पॉवर टूल्स का होना ख़तरानाक है।
- पॉवर टूल्स का रखरखाव करें।चलति पुर्ज़ों के अलाइनमेंट के गड़बड़ाने या बाध्यकारी होने, पुर्ज़ों के टूटने और ऐसी किसी

- भी स्थतिकी जाँच करें, जो पावर टूल के संचालन को प्रभावति कर सकती है।यदि क्षतिग्रस्त है, तो उपयोग से पहले पॉवर टूल को सुधारना होगा। कई हादसे पॉवर टूल के ख़राब रखरखाव के कारण होते हैं।
- काटने वाले उपकरणों को तेज़ और साफ़ रखें। तेज़ कटाई की धार वाले कटिंग उपकरणों के ठीकठीक रखरखाव से इसे बाइंड करने की संभावना कम होती है और इसे नियंत्रति करना आसान होता है।
- कार्य करने की स्थितियों और कार्य निष्पादित करने के लिए, इन निर्देशों के अनुसार, पॉवर टूल, एक्सेसरीज़ और टूल बिट आदिका उपयोग करें। संचालन हेतु पॉवर टूल का इन उद्देश्यों से अलग उपयोग ख़तरनाक़ हो सकता है।

सेवा

केवल समान प्रतिस्थापन भागों का उपयोग करने वाले किसी योग्य मरम्मतकर्ता द्वारा ही अपने पावर टूल की मरम्मत करवाएँ। यह सुनश्चिति करेगा कि पॉवर टूल की सुरक्षा का सही रखरखाव किया गया है।

घर्षण उपकरणों के लिए सुरक्षा नरि्देश

- टूल के साथ दिया गया गार्ड सुरक्षित रूप से पावर टूल से जुड़ा होना चाहिए और अधिकतम सुरक्षा की स्थिति में होना चाहिए, ताकि ऑपरेटर की ओर व्हील का कम से कम हिस्सा निकला हुआ हो. स्वयं को और आसपास खड़े लोगों को रोटेटिग व्हील से दूर रखें. गार्ड ऑपरेटर को टूटे हुए व्हील के टुकड़े और व्हील के साथ आकस्मिक संपर्क से बचाने में मदद करता है.
- अपने पावर टूल के लिए केवल बंधे हुए डायमंड कट-ऑफ़ वृहील्स का इस्तेमाल करें. सिर्फ इसलिए कि आपके पावर टूल से एक्सेसरी को जोड़ा जा सकता है, यह सुरक्षित संचालन के लिए आशवसत नहीं करती है.
- एक्सेसरी की निर्धारित गतिकम से कम पावर टूल पर चहिनति अधिकतम गति के बराबर होना चाहिए. निर्धारित गति में तेज़ चल रही एक्सेसरी टूट सकती है और अलग हो सकती है.
- पहिंचीं का उपयोग केवल सुझाए गए एप्लिकिशन के लिए ही करें. उदाहरण के लिए: कट-ऑफ़ वृहील्स के किनारे को घिंसे नहीं. अपघर्षक कट-ऑफ वृहील का उद्देश्य पेरिफरल ग्राइंडिंग है, एक ओर से लगने वाले बल से यह पहिए टूट सकते हैं
- हमेशा अपने चयनित पहिए के लिए ऐसे अक्षतिग्रस्त वहील फ्लैंज का उपयोग करें जनिका व्यास सही हो. सही वहील फ्लैंज पहिए को सहारा देते हैं जिससे पहिए के टूटने की आशंका कम हो जाती है.
- बड़े पावर टूल में घसि हुए प्रबलित व्हील्स का इस्तेमाल न करें. बड़े पावर टूल के लिए बनाए गए व्हील्स छोटे टूल की उच्चतम गति के लिए उपयुक्त नहीं होते हैं और फट सकते हैं.
- आपकी एक्सेसरी का बाहरी व्यास और मोटाई आपके पावर टूल की क्षमता दर के अंदर होना चाहिए. गलत आकार की एक्सेसरी को पर्याप्त रूप से संरक्षित या निर्यंत्रित नहीं किया जा सकता है.
- पहिंचीं और फ्लैंज का आर्बर आकार पावर टूल के स्पिडिल में ठीक से फिट होना चाहिए. आर्बर होल वाले पहिए और फ्लैंज जो पावर टूल के माउंटिंग हार्डवेयर के समान नहीं होते हैं, वे असंतुलित हो जाएंगे, उनमें अत्यधिक कंपन होगा और वे अन्यित्रित भी हो सकते हैं.
- क्षतिग्रस्त पहियों का उपयोग न करें. प्रत्येक उपयोग से पहले चिप्स और दरारों के लिए पहियों का निरीक्षण करें.

- अगर पावर टूल या व्हील गरि जाता है, तो नुकसान का पता लगाएं या नया व्हील लगाएं. पहिए का निरीक्षण करने और लगाने के बाद खुद को और आसपास खड़े लोगों को रोटेटिंग व्हील से दूर खड़ा करें और एक मनिट के लिए पावर टूल को बना भार के अधिकतम गति पर चलाएं. क्षतिग्रस्त पहिए इस परीक्षण समय के दौरान सामान्य रूप से टूट जाएंगे.
- निजी सुरक्षा उपकरण पहतें. एप्लिकिशन के आधार पर फेस शील्ड, सुरक्षा चश्में या सुरक्षा ग्लासेस पहतें. उपयुक्त हो तो डस्ट मास्क, सुनने संबंधी रक्षक, दस्ताने और शॉप एप्रन पहने जो छोटे छोटे सख़्त या कामकाज के दौरान निकले दुकड़ों को रोकने में सक्षम हैं. आँखों की सुरक्षा के उपकरण विभिन्त संचालनों से उत्पन्न मलने को रोकने में सक्षम होना चाहिए. डस्ट मास्क या रेस्पिरटर आपके संचालन से उत्पन्न कणों को छानने के लिए सक्षम होना चाहिए. लंबे समय तक तेज आवाज़ के संपरक में आने से सुनने की कषमता खो सकती है.
- आसपास खड़े लोगों को कार्य क्षेत्र से सुरक्षित दूरी पर रखें. कार्य क्षेत्र में प्रवेश करने वालों को निजी सुरक्षा उपकरण पहनना आवश्यक हैं. वस्तु या टूटे हुए पहिए के टुकड़े उड़ सकते हैं और संचालन के निकटतम क्षेत्र से बाहर क्षति पहुँचा सकते हैं.
- कार्य करते समय, जहां पर कटांग एक्सेसरी छिपी हुई तारों या अपने कॉर्ड के संपर्क में आ सकती है, ऐसे स्थानों पर पावर टूल को इंसुलेटेड ग्रिपिंग सतहों द्वारा ही पकड़ें. "लाइव" तार के संपर्क में आने वाली कटांग एक्सेसरी से "लाइव" पावर टूल के धातु वाले भाग खुल सकते हैं और ऑपरेटर को बलिजी का झटका लग सकता है.
- कॉर्ड को स्पिनिंग एक्सेसरी से दूर रखें. अगर आप नियंत्रण खो देते हैं तो कॉर्ड कट या फट सकती है और आपका हाथ या कलाई घुमते हुए पहिए के अंदर आ सकता है.
- जब तक एक्सेसरी पूरी तरह से बंद न हो जाए, तब तक पावर टूल को कभी भी नीचे न रखें. स्पिनिगि वृहील सतह को जकड़ सकता है और पावर टूल को आपके नियंत्रण से बाहर कर सकता है
- स्पिनिंग ब्हील को अपनी तरफ़ ले जाते समय, पावर टूल न चलाएं. स्पिनिंग एक्सेसरी के आकस्मिक संपर्क से, यह आपके शरीर को एक्सेसरी की ओर खींचते हुए आपके कपड़ों को खींच सकता है.
- पावर टूल के वायु छिद्रों को नियमित रूप से साफ़ करें. मोटर फैन घर के अंदर की धूल को खींच लेगा और पिसी हुई धातु के अत्यधिक संचय से बिजली के ख़तरे उत्पन्न हो सकते हैं.
- ► पावर टूल को ज्वलनशील सामान के पास संचालित न करें. चिंगारी से इस सामान में आग लग सकती है.
- उन एक्सेसरी का उपयोग न करें जिसमें लिक्विड क्लन्ट की आवश्यकता होती है. पानी या अन्य लिक्विड क्लन्ट के उपयोग का नतीजा बजिली से मौत या झटका हो सकता है.

विष्न और सम्बंधति सुरक्षा नर्देश

झटका, अटके हुए या अवरोधित घर्षण डिस्क की स्वाभाविक प्रतिकिया है। घूमते हुए इन्सर्ट टूल को हुक करने या अवरोधित करने से वह अकसमात रुक जाता है। इससे एक अनयिंत्रति पावर टूल घुमाव की दिशा के विपरीत अवरोधित स्थान पर द्रुत गति से चलता है।

जब उदहारण के लिए, किसी कार्यघटक का घर्षण उपकरण अटकता है या रुक जाता है, घर्षण उपकरण का कोना, जो कार्यघटक में अटका है, निकाल सकता है और उससे घर्षण उपकरण टूट सकता है या एक विघ्न निर्माण हो सकता है। घर्षण उपकरण, अवरोधित स्थल के घूर्णन दिशा के अनुसार ऑपरेटर के

12 | हिंदी

तरफ या उसके वरिद्ध दशािमें घुमने लगता है। इसमें घर्षण उपकरण टट भी शकता है।

एक विचित पावर टूल के गलत या अयोग्य इस्तेमाल के कारण हो सकता है। इसे नीचे दिए गए जैसे, योग्य उपयोग उपायों से टाला जा सकता है।

- पावर टूल पर मजबूत पकड़ रखें और अपने शरीर और हाथ को इस तरह रखें कि वह कि बैक का बल झेलने की अनुमत दिता है. स्टार्ट-अप के दौरान कि बैक या टॉर्क की प्रतिक्रियाओं पर अधिकतम निर्येत्रण के लिए, हमेशा सहायक हैंडल का इस्तेमाल करें. अगर उचित सावधानी बरती जाए, तो ऑपरेटर टॉर्क प्रतिक्रियोओं या कि बैक के प्रभाव को निर्यंत्रित कर सकता है.
- ► अपने हाथ को कभी भी घूमने वाली एक्सेसरी के पास न रखें. एक्सेसरी आपके हाथ पर पुरहार कर सकती है.
- ► अपने शरीर को घूमते हुए पहिए के सामने न रखें. कि कवैक सुनैगिंग पर वृहील की गति के विपरीत टूल को ढकेलेगा.
- कोनों, धारदार किनारों आदि पर काम करते समय विशेष सावधानी रखें और बाउंस करने वाली और स्नैगिग एक्सेसरी से बचें. कोनों, धारदार किनारों या बाउंस वाली एक्सेसरी में घूमने वाली एक्सेसरी को खींचने की प्रवृत्ति होती है और इससे आपका निर्येतरण खो सकता है या यह किवैक कर सकता है.
- सॉ चेन, बुडकार्विग ब्लेड, 10 mm से अधिक घेरे का सेगर्मेटेड डायमंड वृहील या दांत वाला आरी का ब्लेड नहीं जोड़ें. ऐसी ब्लेड लगातार किकवैक और निर्यंत्रण में क्षति पैदा करती हैं.
- पहिए को "जाम" न करें या अत्यधिक दबाव न डालें. कट की अत्यधिक गहराई बनाने का प्रयास न करें. पहिए पर अत्यधिक बल डालने से भार और पहिए के कट में मोड़ने या जाम होने की संवेदनशीलता और किकबैक या पहिया टूटने की संभावना बढ़ जाती है.
- जब वृहील बंधा हुआ हो या किसी कारण से कट को बाधित कर रहा हो, तो पावर टूल को बंद कर दें और जब तक वृहील पूरी तरह से बंद न हो जाए, तब तक पावर टूल को बंद रखें. जब पहिया गतिवान हो तो उसे कट से बाहर निकालने की कोशिश न करें अन्यथा किबैक हो सकता है. पहिए को जाम होने की वजह को हटाने के लिए जाँच करें और सुधारात्मक कार्रवाई करें...
- वस्तु में काटने का संचालन दोबारा शुरू न करें. पहिए को पूर्ण गति तक पहुँचने दें और सावधानीपूर्वक कट में दोबारा प्रवेश करने दें. अगर पावर टूल को वस्तु में दोबारा शुरू किया जाता है तो पहिया जाम हो सकता है, पास आ सकता है या किवेब हो सकता है
- व्हील पचिगि और किकैबैक के जोखिम को कम करने के लिए पैनल या किसी भी ओवरसाइज़ वर्कपीस की सहायता लें. बड़ी वस्तुएँ अपने ही भार के दबाव में आ जाती हैं. वस्तु के नीचे सहारे को कट की रेखा और पहिए के दोनों ओर वस्तु के किनारे के पास रखना चाहिए.
- मौजूदा दीवारों या अन्य अंधेरे क्षेत्रों में "पॉकेट कट" बनाते समय अतिरिक्त सावधानी बरतें. उभरा हुआ वृहील गैस या पानी के पाइप, बजिली की तारों या उन वस्तुओं को काट सकता है. जो किकवैक का कारण बन सकते हैं.

अतरिक्ति सुरक्षा नरि्देश





कान संरक्षण, सुरक्षा चश्मे, धूल मास्क और दस्ताने पहनें। धूल मास्क के लिए कम से कम FFP 2 श्रेणी का एक पार्टिकल फ़ल्टिर

युक्त आधा मास्क प्रयोग करें।

- एक स्थिर प्लेटफ़ॉर्म पर वर्कपीस को सुरक्षित करने और उसे संभालने के लिए क्लैम्प या किसी अन्य व्यावहारिक तरीके का इस्तेमाल करें. अपने हाथ से या शरीर से सामान पकड़ने से, यह अस्थिर हो जाता है और इससे आपका निर्यंत्रण खो सकता है.
- खिपी हुई आपूर्तिलाइनों का पता लगाने के लिए उपयुक्त खोज यंत्रों का प्रयोग करें अथवा स्थानीय आपूर्ति कंपनी से परामर्श करें। बजिली लाइनों के साथ संपर्क में आने से आग या बजिली के झटके के कारण हो सकते हैं। गैस लाइन के क्षतिग्रस्त होने से स्फोट का खतरा हो सकता है। पानी के लाइन में घुसने पर वस्तुओं का नाश या बजिली के झटके लग सकते हैं।
- काम के बाद कटिंग डिस्कि को छूने से पहले इसके ठंडा होने की
 प्रतीक्षा करें। काम के दौरान कटिंग डिस्कि बहुत गरम हो
 जाता है।
- पावर टूल को दोनों हाथों से मजबूती से पकड़ें और पैर को अच्छी तरह एक सुरक्षित जगह पर टिकायें।पावर टूल को दोनों हाथों से सुरक्षित चलाया जाता है।

उत्पाद और सेवा का वविरण



सभी सुरक्षा चेतावनियां और निर्देश सुरक्षा चेतावनियां और निर्देशों का पालन नहीं करने पर बजिली का झटका, आग और गंभीर चोट लगने का खतरा है।

कृपया संचालन नरि्देश के अगले भाग में दिए गए चित्रों पर ध्यान दें।

लक्षति उद्देश्य के लिए उपयोग

पावर टूल, बेस प्लेट के एक स्थरि सपोर्ट के साथ, और सुरक्षात्मक गार्ड के साथ क्षतिजि रूप से इस्तेमाल करते हुए, मुख्य रूप से खनजि सामग्री जैसे उदाहरण के लिए संगमरमर, को बिना पानी के प्रयोग कटाने या घसिने, के लिए लक्षति है। पावर टूल लकड़ी, पुलासुटिक या धातु के कटाई के लिए लक्षति नहीं है।

मैप किए गए घटक

चित्रति घटकों का संख्यांकन ग्राफ़िक्स पृष्ठ पर दर्शाए गए पावर टूल के चित्रण के अनुसार है।

- (1) चाल्/बंद सवचि
- (2) चालू/बंद सुवचि कके लिए लॉकिंग कुंजी
- (3) हस्त हैंडल (इन्सुलेट की गई हैंडल सतह)
- (4) कट की गहरे मापक
- (5) कट गहराई क्लैंप की स्थापना के लिए थंब पेंच
- (6) डायमंड बलेड^{A)}
- (7) घरषण धुरी का घुमाव दिशा तीर
- (8) सुरकषागारड
- (9) बेस पलेट
- (10) ड्राइवधुरी
- (11) ओ-रगि
- (12) अटैचमेंट फलैंज
- (13) टेंशनगि फ्लैंज
- (14) रिग कंजी
- (15) टेंशनगि पेंच

- (16) षट्कोणीय सॉकेट रचि
- (18) कार्बन ब्रश
- ति दिखाया गया या वर्णित सहायक उपकरण मानक डिलीवरी में शामिल नहीं है।संपूर्ण सहायक उपकरण को हमारी सहायक उपकरणों की श्रेखला से प्राप्त किया जा सकता है।

तकनिकी डेटा

पत्थर का सॉ		GDC 155
वास्तु क्रमांक		3 601 CA0 2F.
रेटेड इनपुट पावर	W	1550
निष्क्रिय गत	मनि ^{∙1}	8600
डायमंड कर्तन डि्मक का अधकितम व्यास	mm	150-155
ब्लेड की न्यूनतम मोटाई	mm	1,6
कटगि डसि्क की अधकितम मोटाई	mm	2,2
अटैचमेंट छिि्र	mm	20
अधिकतम कट गहराई	mm	47
EPTA-Procedure 01:2014 वधिकि अनुसार वजन	kg	3,4
सुरक्षा श्रेणी	2 2 2	<u></u>

ुं आंकड़े [U] के 230 V एक रेटेड वोल्टेज के लिए है। विभिनिन वोल्टेज में और देश-विशिष्ट डिझाईनों में यह प्रमाण अलग हो सकते हैं।

मोंटा

 पावर टूल पर कोई कार्य करते समय प्लग को सॉकेट से निकाल लें।

धूल / चपि वैक्यूम निष्कर्षण

सामग्री की धूल जैसे युक्त लीड पेंट, कुछ लकड़ी की प्रजातियों, खनजि एवं धातु हानिकारक हो सकते है। ऐसी धूल को स्पर्श करने या सांस लेने के परिणामस्वरूप उपयोगकर्ता अथवा संपर्क में आने वाले व्यक्तियों को एलर्जी प्रतिक्रिया हो सकती है और/ अथवा शवसन संबंधी बीमारी हो सकती है।

विशिषिट धूल जैसे ओक या बीच की धूल के रूप में विशिष रूप से लकड़ी उपचार के लिए योजकों का संयोजन किए हुए कार्सनीजन (क्रोमेट, परिक्षक लकड़ी), वर्गीकृत किए गर्ये हैं। एसबेस्टस युक्त सामग्री पर केवल विशिषज्ञों द्वारा काम किया जा सकता है।

- कार्यस्थल के लिए अच्छा वेंटीलेशन प्रदान करें।
- यह फ़लिटर वर्ग P2 के साथ एक सुरक्षात्मक मास्क पहनने के लिए सिफारिश की गई है।

जिन सामग्रयों पर काम करना है, उनके संदर्भ में अपने देश में लागु प्रावधानों का ध्यान रखें।

 कार्य स्थल पर धूल को जमा न होने दें। धूल में आसानी से आग लग सकती है।

डायमंड बुलेड डार्ले/बदलें (चतिर Aदेखें)

- डायमंड ब्लेड डालते या बदलते वक्त सुरक्षात्मक दस्ताने पहनें।
- काम करते समय डायमंड ब्लेड काफी गर्म हो जाते हैं, इसलिए उनके ठंडा होने से पहले उन्हें स्पर्श न करें।

- सदैव सही आकार एवं तकनीकी डाटा में निर्दिष्ट आकार के छिदर वाले डायमंड बलेड का ही इसतेमाल करें।
- केवल हीरे से आवरित ब्लेड का उपयोग करें। सेगमेंटेड डायमंड डिस् के में केवल नेगेटिव कटिंग एंगल होने चाहिए और सेगमेंट के बीच अधिकतम 10 mm का सलॉट होना चाहिए।

डायमंड कर्तन डसिक को लगाएं।

- डायमंड ब्लेड (6) एवं अन्य क्लैंपगि पार्ट्स को लगाने से पहले अचछी तरह से साफ़ कर लें।
- ओ-रगि (11) के साथ मॉउंटगि फ्लांज (12) को ड्राइव स्पडिल (10) पर लगाएं।
- मॉउंटिंग फ़्लान्ज (12) पर डायमंड ब्लेड (6) रखें।डायमंड ब्लेड (6) की तीर की दिशा और सुरक्षात्मक आवरण (8) पर सथित तीर की दिशा एक होनी चाहिए।
- क्लैंपगि फ्लैग (13) को फिट करें और क्लैंपगि स्क्रू (15)में स्क्रू करें।
- क्लैंपगि फ़्लान्ज (13) को रिंग स्पिनिर (14) के साथ पकड़ें और क्लैंपगि स्क्रू (15) को षट्कोणीय सॉकेट रिंच (16) के साथ कर्सें।

डायमंड-कर्तन डस्कि नकालें

- क्लैंपगि फ़्लान्ज (13) को रिंग स्पिनर (14) के साथ पकड़ें और षट्कोणीय सॉकेट रिंच (16) साथ क्लैंपगि स्क्रू (15)को ढीला करें।
- ड्राइव स्पडिल (10) से क्लैम्पिंग फ्लैग (13) और डायमंड बलेड (6) को निकालें।

संचालन

संचालन परकार

- पावर टूल पर कोई कार्य करते समय प्लग को सॉकेट से निकाल लें।
- कार्य करते समय, जहां पर कटिंग एक्सेसरी छिपी हुई तारों या अपने कॉर्ड के संपर्क में आ सकती है, ऐसे स्थानों पर पावर टूल को इंसुलेटेड ग्रिपिंग सतहों द्वारा ही पकड़ें. "लाइव" तार के संपर्क में आने वाली कटिंग एक्सेसरी से "लाइव" पावर टूल के धातु वाले भाग खुल सकते हैं और ऑपरेटर को बिलजी का झटका लग सकता है.

कटिंग डेप्थ को पहले से निर्धारित करें (चित्र B देखें)

 कट की गहराई का चयन केवल पावर टूल बंद होने की स्थिति में किया जाता है।

कट की गहराई को वर्कपसि की मोटाई से समायोजति करें। सर्वोत्तम परणािमों के लिए, डायमंड ब्लेड सामग्री से लगभग 2 mm फैलाना चाहिए।

 थंबस्क्रू (5) को ढीला करें। कम गहराई में काटने के लिए पावर टूल को बेस (9) से दूर करें, एवं अधिक गहराई में काटने के लिए पावर टूल को बेस (9) की तरफ सरकायें कटिंग डेप्थ स्केल (4) पर वांछति आयाम सेट करें। विगे नट (5) को पुनः कर्से

कार्यान्वति करना

 वोल्टेज नोट करें! पावर का स्रोत का वोल्टेज दर्ज़ा प्लेट पर विनिर्देशों के बजली के उपकरण से मेल खाना चाहिए। 230 V के साथ चिह्निति बजिली उपकरण भी 220 V से कनेक्ट कर सकते हैं।

14 | हिंदी

चाल करना/बंद करना

- पावर टूल चालू करने के लिए स्विच (1) ऑन/ऑफ को दबाये रखें।
- ऑन/ऑफ़ स्वचि (1) को निर्धारित करने के लिए कैप्स लॉक कुंजी (2)दबाएं।
- पावर टूल को बंद करने के लिए, ऑन / बंद स्वचि (1) दबाएं, अगर यह लॉकिंग बटन (2) से बंद हैं तो थोड़े देर के लिए ऑन/ ऑफ़ सवचि (1) दबाकर छोड़ दें।
- इस्तेमाल करने से पहले डायमंड ब्लेड की जांच करें।डायमंड ब्लेड को ठीक से माउंट किया जाना चाहिए ताकि यह स्वतंत्र रूप से घूमने में सक्षम हो।बिना लोड दिए कम से कम 1 मिनट के लिए चला कर जांच लें।क्षतिग्रस्त, आउट-ऑफ-द-राउंड या बाइब्रेटिगिडायमंड ब्लेड को इस्तेमाल में नहीं लाएं। क्षतिग्रस्त डायमंड कर्तन डिस्क टूट सकते है और चोट का कारण बन सकते हैं।

कार्य नरिदेश

- भारवाही दीवारों को काटने समय सावधानी बरतें, इसके लिए
 "संरचनात्मक विश्लेषण से समुबंधित निर्देश" अनुभाग देखें।
- पॉवर टूल को बहुत ज्यादा लोड नहीं करें, कि वह एकदम ही बैंड हो जाएं।
- पावर टूल का अधिक उपयोग करने के बाद उसे ठंडा होने के लिए कुछ मिनट उपयोग में नहीं लाएं।
- अगर आप कठिन साहित्यों से काम कर रहे हों, जिस के कट का आयाम 20 mm से अधिक हो, उदहारण के लिए, बीटोन, अधिकांश क्कार्य पद्धतियों में, इंजन पर ज्यादा भारना डालें।
- वर्कपीस को करें, जब तक की यह अपने वजन के सापेक्ष सुरक्षति नहीं हो जाता।
- ▶ पावर टूल को केवल सुखी कटाई करने के लिए पुरयोग करें।
- काम करते समय डायमंड ब्लेड काफी गर्म हो जाते हैं, इसलिए उनके ठंडा होने से पहले उन्हें सुपर्श न करें।

कटिंग डिस्क को आघात, टकराव और ग्रीस से बचाएं। कटिंग डिसक पर बगल की ओर से दबाव नहीं डालें।

चलते हुए डायमंड-कर्तन डि्मक को एक तरफ से दबाव देकर ना

अतिकठिनि सामग्री को कटाने के समय, उदाहुनार्थ बजरी सामग्री हिरा युक्ता कर्तन डिम्क ज्तादा गरम हो जाती है और उससे क्षतिग्रस्त हो जाती है। एक हीरे के कर्तन डिस्क से निश्चित धूल कण उसके अंतर चले जाते हैं।

ऐसी स्थिति मिं कटाई रोकें एवं हरि। युक्त कटाई डिस्क को कुछ पलों के लिए खली चलने दें जिससे वह ठंडा हो जाए।

क्लाफ़ी काम बढ़ चुका है और एक परिधीय रिम धुल को कम करने के लिए एक सुस्त हीरा पहिया के संकेत मिल रहे हैं। अपघर्षक सामग्री आप छोटे कटे स्लॉट्स में जैसे चुना वाले पत्थर से फरिसे तेज कर सकते हैं।

कट लगाने की दशा (चत्रिर Cदेखें)

पावर टूल कोएक सामान दबाव के साथ चलन चाहिए। अन्यथा यह खतरा होता है की वह ,स्लॉट में से **अनयिंत्**रति दबने का खतरा हैं।

स्टैटिक्स के लिए निर्देश

लोड बेर्रोग दीवारों की आवश्यकताएं DIN 1053 भाग 1 अथवा देश अनुसार मानकों के अधीन है। यह नयिमोंका पालन अनवािर्य हैं। काम शुरू करने से पहले जिम्मेदार स्टैटिक शलि्पकार या प्रासंगकि घटक सलाहकार से सलाह लें।

देखभाल एवं सर्वसि

देखभाल एवं सफाई

- पावर टूल पर कोई कार्य करते समय प्लग को सॉकेट से निकाल लें।
- अच्छी तरह काम करने के लिए और सुरक्षा के लिए, पावर टूल्स एवं वेंटलिशन सुलॉट्स को साफ़ रखें।

कनेक्शन केबल को बदलने की आवश्यकता पड़ने पर, सुरक्षा से सम्बंधति खतरों एवं जोखिमों से बचने के लिए इसे सरिफ Bosch द्वारा या Boschग्राहक सेवा केंद्र द्वारा बदला जाना चाहिए या उनके द्वारा अधिकृत किया जाना चाहिए।

कार्बन ब्रश बदलें (चत्रि Dदेखें)

हरेक 2-3 महीने में कार्बन ब्रश की लंबाई की जाँच करें और यदि आवश्यक हो तो दोनों कार्बन ब्रश को बदलें।

कभी भी सर्फि एक कार्बन ब्रश ना बदलें!

नोट: केवल Bosch आवरण वाले कार्बन ब्रश का उपयोग करें जो आपके उत्पाद के लिए तैयार किया गया है।

- पेचकश से (17) आवरण को ढीला करें।
- स्प्रिंग एक्स के नीचे के ब्रश (18) को बदलें और आवरण को पनः कसें।

ग्राहक सेवा एवं उपयोग सलाह

ग्राहक सेवा आपके उनके उत्पादनों तथा देखभाल के विषय में आपके सवालों का जवाब देगी।स्पेयर पार्ट्स के बारे में अधिक जानकारी और वसितृत (एक्सप्लोडेड) दृश्य यहां भी मलि सकते

है: www.bosch-pt.com

Bosch की एप्लीकेशन परामर्श टीम हमारे उत्पादों और उनके सहायक उपकरणों के संदर्भ में आपके सभी प्रश्नों में आपकी सहायता करेगी।

पत्राचार के दौरान तथा स्पेयर पुर्जों का ऑर्डर देते समय, उत्पाद के लेबल पर दर्ज 10 अंको वाली आर्टिकल संख्या अवशय परदान करें।

भारत

Bosch Service Center 69, हबीबुल्लाह रोड, (पीएसबीबी स्कूल के आगे), टी. नगर चेन्नई–600,077 फ़ोन: (044) 64561816 Bosch Service Center

Bosch Service Center 18, सामुदायिक केंद्र फ़ेस 1, मायापुरी नई दल्ली-110064 फ़ोन: (011) 43166190

नपिटान

पावर टूल्स, सहायक उपकरणों और पैकेजिंग का पुनर्चक्रण पर्यावरण के अनुकूल कयाि जाना चाहिए।



बजिली उपकरणों का निपटान घरेलू कचरे में न करें!

Bosch Power Tools